

## ELECTROLUX HOME PRODUCTS PTY LTD

ABN 51 004 762 341

Technical Bulletin Nº DWB132

Issue: 1 Date: 03/13

# END OF CYCLE LED EDW500 ROTARY CONTROL PCB's

## Applicable Product

DX103WK/91151903109 DX103SK/91151903209 and 52C850WK/91151902909 52C850SK/91151903009 (NZ)

#### Concern

The replacement of rotary control boards unnecessarily.

## Dishwasher Factory

Due to changes in European Government laws regarding dishwashers in standby mode, the dishwasher factory has introduced new software that does not allow the "End of Cycle" LED to remain on until the door is opened.

Another notable modification to the EDW500 Rotary Electronic Controller is the colour of it. The housing colour changed from white or cream to grey. Grey was chosen because it proved to have the best results compared to the white or cream housings for 'overshining' or 'LED glow through'. Overshining or LED glow through is described as illumination of other indicators close to or next to the one that is actually lit. The grey housings gave the best results.



## Service Technicians / Spare Parts

If the only issue is the End of Cycle LED doesn't stay illuminated, there is nothing wrong with the board. Customer explanation of operation is all that is required; use Defect Code 54.

### **Technical Services**

Following up software & housing colour modifications for all other dishwashers we procure from Europe.